

ILP-15 Streetworks Column

Allows easy and accurate orientation with GPS alignment from ground level

This product was specifically designed to overcome problems with existing street furniture columns on the market. Problems observed include:

- Column totally reliant on exact orientation of root section when landed
- Red marker denoting the centre of orientation of sector 1 often incorrect by up to 10°
- Centre line of antenna not directly behind factory red marker
- Marker on shroud 15m in the air making orientation from ground level impossible

Accurate orientation of antennas can therefore be difficult, impacting on the network optimal radio plan.

The ILP-15 allows accurate orientation with GPS alignment from ground level. Lead-time for delivery is 4 weeks.

